



Compare **RABBIT** to other manufacturers...the choice is clear!



- Made in the USA • HEPA filtration to 0.3 microns • Thermal motor shut off
- Handle Vac model attaches directly to your floor machine • UL tested and approved
- New and improved 2-stage motor • 7 year motor warranty (Best in the industry)
- Lightweight • Ergonomic • Carpet & Rug Institute Gold Certified

| | AVERAGE | | | GOOD | | | BEST |
|--|--|---|---|--|--|---|---|
| Motor Saver™ ★ = Best in Class quality/ value ⚬ = Poor Value AVG. = Average Value | | | | | | | |
| Manufacturer: | | | | | | | ★ |
| HEPA | YES ★ | YES ★ | NO | NO | YES ★ | YES ★ | YES ★ |
| Vacuum hose is full size into the vacuum body. 90° hose cuff clogs & reduces airflow | NO <i>Restricted air flow</i> | YES ★ | YES ★ | NO <i>Restricted air flow</i> | NO <i>Restricted air flow</i> | NO <i>Restricted air flow</i> | YES ★ |
| Thermal Motor Shut Off (Eliminates Motor Damage) | NO... <i>thermal shut-off</i> ⚬ | NO... <i>thermal shut-off</i> ⚬ | NO... <i>thermal shut-off</i> ⚬ | NO... <i>thermal shut-off</i> ⚬ | NO... <i>thermal shut-off</i> ⚬ | NO... <i>thermal shut-off</i> ⚬ | YES ★ <i>Thermal shut off protects the motor from extreme heat & restarts when cool</i> |
| Underwriters Laboratories Inc. Tested & Approved | NO | NO | NO | YES ★ | NO | NO | YES ★ |
| Industry best rated motor | <i>Could not identify motor MFG</i> | <i>Could not identify motor MFG</i> | YES ★ | NO | YES ★ | YES ★ | YES ★ |
| Housing warranty | 2 Yrs. ⚬ | 2 Yrs. ⚬ | Lifetime ★ | 3 Yrs. ⚬ | Lifetime ★ | Lifetime ★ | Lifetime ★ |
| Motor & pigtail warranty (Most common backpack failure) | 2 Yrs. ⚬ | 2 Yrs. ⚬ | 5 Yrs. AVG. | 3 Yrs. ⚬ | 3 Yrs. ⚬ | 3 Yrs. ⚬ | 7 Yr. ★ <i>Best in the Industry</i> |
| Actual weight (Unit with all tools no power cord) | 13.2 lb | 11.2 lb | 15.6 lb ⚬ | 11.2 lb | 12.6 lb | 13.0 lb | 8 lb ★ |
| Adjustable chest strap | YES ★ | NO | NO | NO | YES ★ | YES ★ | YES ★ <i>Backpack model only</i> |
| Ergonomic back rest | NO | NO | YES | NO | NO | NO | YES ★ <i>Backpack model only</i> |
| Molded in cord holder | NO <i>Easy to break</i> | NO <i>Easy to break</i> | NO <i>Easy to break</i> | NO <i>Easy to break</i> | NO <i>Uses flimsy cord retainer</i> | NO <i>Easy to break</i> | YES ★ <i>Molded In</i> |
| Converts to blower | NO | NO | YES | NO | NO | NO | YES ★ <i>Backpack model only</i> |
| Private label (Best option to promote your brand and combat internet discounts) | NO | NO | YES | NO | NO | NO | YES ★ |
| RATINGS TOTALS: | ★ 2 ⚬ | ★ 2 ⚬ | ★ 3 ⚬ 1 AVG. | ★ 1 ⚬ | ★ 4 ⚬ | ★ 3 ⚬ | ★ 14 |
| NOTES: | <ul style="list-style-type: none"> - Poor warranty - No thermal shut off - Internet discount - Made in China | <ul style="list-style-type: none"> - Poor warranty - No thermal shut off - High motor heat - Internet Discount - Made in China | <ul style="list-style-type: none"> - Very heavy - Very big physical size - Expensive pigtail size - Made-in-China <p>Have not tested the new made-in-China replacement of the Raven</p> | <ul style="list-style-type: none"> - Thin plastic body - High motor heat - Exhaust blocked removal of exhaust filter to view airflow restriction - Made in China | <ul style="list-style-type: none"> - Poor design - Expensive bags - Thin plastic body - Very big physical size - Made in China & Mexico | <ul style="list-style-type: none"> - Expensive - Very big physical size - 90° cuff at lid cloggs, restricts airflow - Expensive switch repair - Expensive pigtail repair - Made in China & Mexico | <ul style="list-style-type: none"> - Light weight lbs - 7 yrs motor warranty - Non clogging hose entry into body - HEPA filtration standard - UL tested and approved - Motor saver standard - Made in USA - HEPA motor saver standard |